

0034

MEC

Mangum
Engineering
Consultants

388 East Boynton Road • Kaysville, Utah 84037 • (801) 544-3641

RECEIVED
AUG 22 1989

Rick Smith
Utah Division of Oil Gas & Mining
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

DIVISION OF
OIL, GAS & MINING

22 August 1989

Mr. Smith,


Ref: Cross Conveyor, NOV-89-26-18-1, Bear Canyon Mine, Co-Op Mining
Company, ACT/015/025, Emery County, Utah.

#2

Attached are two copies of Plate 2-4 updated to show the installation of the Cross Conveyor from the upper seam to the Hiawatha Seam Conveyor system. Also attached are two copies of the following pages which have been modified to reflect this change; 3-7, 3A-2, 3A-6, and 3A-7. This modification of the coal handling facility should measurably reduce the impact from coal fines on the environment and decrease the problem with fires that has occurred repeatedly in association with the recovery bin.

If there are any additional items that require attention please let me know.

Thank you,



Kimly C. Mangum, P.E.

Permitting & Compliance Consultant.